US009409263B2

(12) **United States Patent**
Auguste et al.

(10) **Patent No.: US 9,409,263 B2**
(45) **Date of Patent: Aug. 9, 2016**

(54) **METHOD FOR DETECTING AN ERROR IN THE INSTALLATION OF A SEAL IN A MASTER CYLINDER**

(75) Inventors: **Antony Auguste**, Villiees/Marne (FR); **Laurent Lhuillier**, Le Blanc Mesnil (FR); **Nicolas Quiniou**, Villemonble (FR); **Daniel Grech**, Lamorlaye (FR); **Carole Charpentier**, Montmorency (FR)

(73) Assignee: **ROBERT BOSCH GMBH**, Stuttgart (DE)

(*) Notice: Subject to any disclaimer, the term of this patent is extended or adjusted under 35 U.S.C. 154(b) by 395 days.

(21) Appl. No.: **13/994,511**

(22) PCT Filed: **Nov. 16, 2011**

(86) PCT No.: **PCT/EP2011/070216**

§ 371 (c)(1),
(2), (4) Date: **Oct. 30, 2013**

(87) PCT Pub. No.: **WO2012/079900**

PCT Pub. Date: **Jun. 21, 2012**

(65) **Prior Publication Data**

US 2014/0041221 A1 Feb. 13, 2014

(30) **Foreign Application Priority Data**

Dec. 17, 2010 (FR) 10 04952

(51) **Int. Cl.**

B23P 15/10	(2006.01)
B60T 11/232	(2006.01)
B60T 11/236	(2006.01)
B60T 17/22	(2006.01)
F15B 7/08	(2006.01)
F15B 19/00	(2006.01)
F16J 15/32	(2016.01)

(52) **U.S. Cl.**

CPC ***B23P 15/10*** (2013.01); ***B60T 11/232*** (2013.01); ***B60T 11/236*** (2013.01); ***B60T 17/221*** (2013.01); ***F15B 7/08*** (2013.01); ***F15B 19/005*** (2013.01); ***F16J 15/3236*** (2013.01); ***F16J 15/3268*** (2013.01); *Y10T 29/49236* (2015.01); *Y10T 29/49764* (2015.01); *Y10T 29/49776* (2015.01)

(58) **Field of Classification Search**

CPC B23P 15/10; B60T 11/236; B60T 17/221; B60T 11/232; F16J 15/3268; F16J 15/3236; F15B 19/005; F15B 7/08; Y10T 29/49776; Y10T 29/49764; Y10T 29/49236

See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

4,698,999 A * 10/1987 Trick G01N 3/12 73/40

4,989,498 A 2/1991 Mori et al.

FOREIGN PATENT DOCUMENTS

CN	1458890	11/2003
CN	1623831	6/2005

(Continued)

Primary Examiner — John C Hong

(74) *Attorney, Agent, or Firm* — Norton Rose Fulbright US LLP

(57) **ABSTRACT**

A method is described for detecting an incorrectly installed seal in a master-cylinder having a seal. The master cylinder is subjected to a pressure comprised between approximately 0.3 and 0.6 MPa at the conclusion of master-cylinder assembly and, if there is a drop in the pressure, the seal is considered to have been installed in reverse in the groove of the master cylinder.

3 Claims, 3 Drawing Sheets