
10
14
Autoloader
18
Laser
12
40
Laser beam path 32
Load arm
Fresh panel
Processed panel
52
Fine Camera
Coarse Camera
50
54
28
24
Vacuum
34
22
30
20
28
48
Load arm
38
26
System Controller
Chuck
42
16
Thickness Measurement System
46
Thickness
Human Interface Computer (CAD coordinates)
56
44
36

FIG. 1